

# Dictation Products Service Bulletin

CSA-15

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

Model: BM-89, DTI-800

No. 29

Subject: Circuit Change Required for BM-89 to be used  
with DTI-800

Date: June 15, 1995

## Symptom:

(\*\*)


BM-89 does not work with telephone interface DTI-800.

## Solution:

BM-89 requires the following parts added in order to work with DTI-800.

Q'TY	DESCRIPTION	PART NUMBER
2	CERAMIC, 0.1UF 16V	1-162-851-11
1	RESISTOR, 220KOHM 1/4W	1-247-887-00

- Install 0.1 uF capacitor between CN104 Pin 2 and IC106 Pin 13.
- Install 0.1 uF capacitor and 220Kohm resistor in series between CN104 Pin 3 and the junction of IC112 Pin 49 and C102.
- Use isolation material as necessary.





Filename: DIC0029.SB  
Directory: J:\SBDOC\JUN95  
Template: C:\WINWORD\TEMPLATE\S\_BULL.DOT  
Title:  
Subject:  
Author: Hoyt Wing Lee  
Keywords:  
Comments:  
Creation Date: 06/15/95 9:35 AM  
Revision Number: 2  
Last Saved On: 06/15/95 9:35 AM  
Last Saved By: Hoyt Wing Lee  
Total Editing Time: 1 Minute  
Last Printed On: 04/01/96 9:04 AM  
As of Last Complete Printing  
Number of Pages: 2  
Number of Words: 147 (approx.)  
Number of Characters: 842 (approx.)