

SONY

Dictation Products Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: RDI-500/RD-400, RDI-500/RD-500

No. 6

Subject: Telephone Line Disconnection

Date: September 20, 1991


Symptom:
(22)

Intermittently RDI-500 disconnects the telephone line right after the connection is made.

Solution:

On RD-400 and RD-500 Audio Board, install 1 μ F 50V capacitor, 1-126-301-11, at IC106 and IC306 pin 6 for + and pin 4 for -.

RD-400, RD-500 AUDIO BOARD, MOUNT SIDE



NOTE: This happens only on certain phone lines.

Reference: YK

PRINTED IN U.S.A.
CSA-15991-1

Dictation
CSA-15