


Model: KP-53HS10, KP-61HS10**No. 526****Subject:** Banding Symptom
With Progressive Scan input on Video 5**Date:** March 7, 2001**Symptom:**
(133X)

During certain scenes of certain DVD movies titles with progressive scan DVD players. A slight horizontal banding maybe noticed on the following edge of a moving image.

Cause

Sandcastle "clamp" pulse overlaps video signal causing clamping errors.



Three thin horizontal lines and one thick one at the bottom before the lower part of the black bar of the letterboxed imaged. This scene occurs during the first second or two of chapter 6 of Star Trek 2.

Solution: If the customer should complain of this symptom please incorporate the following Service Data change.

1. Change in the Service Mode PWM1 from 0 to 42.
2. Confirm Flash Focus operation in the Service Mode.

Ref	Former Setting	New Setting
PWM1	0	42