PC-Driven Audio Sweep Analyser (March 1996): On page 65, in the schematic for the analyser section of the circuit, the 47k resistor connecting from the rotor of trimpot RV4 to the non-inverting input of U2a is labelled incorrectly as R24. It should be shown as R28.