

The situation is fast approaching where construction should not be attempted until after a reasonable period has elapsed to enable any errors to be recorded in the "Notes and Errata".

The latest effort was in the Selectalott regarding IC1 (4017) where the pin numbers are reversed. Luckily I had used sockets and it was only a matter of inverting IC1 in the socket for it to work perfectly. Hope to win Lotto eventually with this device.

T. V. Askin,  
Doonside, NSW.