

SONY®

Dictation Products Service Bulletin

Sony Service Company • Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: M88V

No. 11


Subject: Part Numbers Switched In Service Manual

Date: February 19, 1992

Symptom:
(**) The part numbers for S-102 and S-106 are switched in the Service Manual.

Solution: Please correct your Service Manual with the part numbers listed below:

REFERENCE NUMBER	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
S-102	SWITCH (TAPE SPEED)	1-571-506-21	1-571-277-11
S-106	SWITCH (MIC SENSOR)	1-571-277-11	1-571-506-21



Reference: L0760

PRINTED IN U.S.A.
CSA-15292-2

CSA-15 Personals