

# TV Products Service Bulletin

CSV-1

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

---

**Model:** KV-32XBR100  
KP-53XBR45, 61XBR48

**No.** 295

**Subject:** Can't Swap PIP (Main & Child Picture)

**Date:** March 11, 1996

**Symptom:**

( 122 ) Customer can not Swap PIP (Main & Child Picture).

**Solution:**

Please Check Input Signal Setup in the Menu screen as follows:

1. Open Menu screen and select Input/Output Icon on the screen
2. Check input signal selection. If "TV Out" is selected, Please switch to "Edit Out" or "Monitor Out".
3. Exit from Menu and confirm PIP function.



