

□ In September 1985 issue I noticed some mistakes. The circuit diagrams of Electronic Auto Dipper and Automatic Mast Light Switch were interchanged. Please try to avoid such printing mistakes. I hope EFY becomes a zero error magazine.

K V N R KRISHNA

Eluru