

## Radiation counter

Sir—With reference to my article *Radiation Counter* in the March 1967 issue. I would draw readers' attention to an error on the e.h.t. circuit Fig. 3.

The base bias resistor (R16) should be shown connected to the negative supply rail and not the collector of the transistor as it appears in the magazine. I would think that the latter configuration would severely damp the oscillatory circuit, however the effect on its performance could only be found by experiment (it may in fact work like this). This error also renders the underside wiring diagram Fig. 5 incorrect.

P. F. Bretherick,  
Eastcote,  
Ruislip,  
Middlesex.