Write to Letters, Electronic

CORRECTIONS Some errors in "The Lost Art of Regeneration" (*Electronics Now*, March 1994) should be corrected. In Fig. 1, Diode D1 should be reversed. In Fig. 8, pin 7 of ICI should be connected to the positive side of battery B1, and the missing value of capacitor C6 is 0.1 µF. In Figure 11, the schematic should show that the collector of Q1, capacitor C1 and L2 are all connected because the crossed wires are connected. I hope that no reader's have been in-

DECEMEDATION DESYAMINED

convenienced by these errors.

CHARLES KITCHEN Wilmington, MA