

SONY

Dictation Products Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: BM-570

No. 15

Subject: Modification To Disable Search Function

Date: March 20, 1992


Symptom:
(**)

When rewinding a tape with sound recorded on CUE track, it stops and beeps due to the search function of this model.

Solution:

The following modification eliminates the search function, but the record function of LTR and SEC marks is not affected.

Make a solder bridge on S102, 4/4, REC side.



Reference: YK

PRINTED IN U.S.A.
CSA-15392-1

Dictation
CSA-15