


Model: KV-20FS12**No.** 505**Subject:** Beznet and Control Door Part Change**Date:** October 16, 2000**Symptom:****(xxxx)** Door is hard to open.**Solution:**

The beznet and control door were changed in order to add a retainer to improve the operation of the (Ref. 6) control door.

The new Retainer Door and Beznet are not interchangeable with the older door and Beznet.

Ref	Description	Part Number
1	Beznet Ass'y	X-4037-392-6
6	Retainer Door	4-078-807-01
Not shown	Retainer	3-703-574-01





Original Bezel with no retainer



New Bezel with retainer



Original Door



New Door with hooks for retainer catching