


REVISIONS				
ZONE	REV.	DESCRIPTION	DATE	APPROVED
	A	CORRECTED TO PCB, RELEASE	11/17/92	
	B	ADDED C126	12/17/92	
	C	CHG'D GYRATOR PARTS TO 1%	12/21/92	
	D	ADDED C127	12/22/92	
	E	ADDED R143, 44, 45 & R146	12/29/92	
		REMOVED C126, C127, R143, 44, 45 & R146		

B7 F ADDED μ CAB II CHANGES 11-4-94 DJT



NOTES:

1. R143, R144, R145 & R146 ARE NOT NORMALLY STUFFED: THEY ARE TO BE INSTALLED ONLY WHEN IT IS NECESSARY TO TRIM THE GAIN OF THE ASSOCIATED GYRATOR.
2. PCB 680098 REV F.

PROPRIETARY <small>THIS DRAWING DOCUMENT CONTAINS INFORMATION WHICH IS PROPRIETARY TO AND IS THE PROPERTY OF ADA SIGNAL PROCESSORS, INC. AND MAY NOT BE USED, REPRODUCED OR DISCLOSED IN ANY MANNER WITHOUT THE EXPRESSED WRITTEN CONSENT OF ADA SIGNAL PROCESSORS, INC.</small>		ADA SIGNAL PROCESSORS, INC. 420 LESSER STREET OAKLAND, CA 94601	
DATABASE FILE: UCABA.DBF		SCHEMATIC, MICRO-CAB II AUDIO CHANNEL A	
CHECKED BY:	ENGR: RTS	SIZE D	DRAWING NUMBER 807
APPROVED:	SCALE:	DATE: 30-DEC-94	SHEET 1 OF 3