

In "A/D Temperature Converter" (December 1976), there is an error in the etching and drilling guide shown in Fig. 2 in the area of *D1*, *R7*, and *R8*. The corrected guide is shown below.

