

Notes & Errata

Programmer for dsPICs & PICs, May 2008: Table 4 showing the jumper settings is incorrect for PICs requiring the external adaptor PCB (ie, the 10F, 12F and 16F63X/67X/68X devices). The V_{pp} connection must be selected using either JP4 or JP3.

For example, for the PIC12F675, JP3 should be inserted to connect its pin 4 to the V_{pp} supply. Check the data sheet for the device you are using to verify which pin is V_{pp} .

Stereo DAC (September-November 2009): the 300 Ω resistor across CON1 should be changed to 82 Ω for improved coaxial cable termination. This affects Fig.2 and the parts list in the September 2009 issue, as well

as Fig.5 and Table 1 in the October issue.

Two TOSLINK-S/PDIF Audio Converters (October 2010): the 300 Ω resistor on the S/PDIF to TOSLINK board should be changed to 82 Ω for improved coaxial cable termination. This affects Fig.1, Fig.3, Table 1 and the parts list.

Quizzical (October 2011): in the specifications panel on page 18 it states that the Quizzical can handle SD cards up to 2GB. While correct at the time, Tenda Electronics have advised that the latest TDB830 MP3 modules will now handle SD cards up to 8GB.