POINTS ARISING

P.E. ORION (January and February 1975)

In the components list the case was quoted as being GB3, this should be GB1.

The mains transformer SL8 can be obtained direct from Gardners Transformers Ltd. see Market Place page 234.

P.E. MINISONIC—3 (January 1975)

In the components list, for the H.F. Detector transistor, TR1 was not listed. This should be type RC184.

DIGITAL LEAF (January 1975) See Market Place page 234.

MARINE SPEEDOMETER (February 1975)

Due to poor reproduction of Fig. 3 it is impossible to identify the breaks in the copperstrips of the Veroboard. Assuming the board is annotated from the top left corner, strips A to NN and holes 1 to 46, the breaks should be made at the following points: 26G, 5J, 127, X38, CC19, DD19, Esta, FFI0, HH19, III9, L138.

Practical Electronics March 1975