

ASCII-to-Morse-Code Interface

If you wish to order the kit from Suncoast Technologies for the above-

mentioned project (February 1994, page 36), the correct telephone number to call is (904) 596-7599.

Using the World's Most Accurate Frequency Standard

The above-mentioned project is a three-part series which appeared in the January, February, and March 1994 issues. There is a slight error on the PC board layout for Part 1,

the WWVB Receiver, which appeared in February, page 23, Figure 5. Shown below is the correct foil pattern and a simple cut-and-jumper fix for the one we printed. The RF amp will still work without this fix; it just won't work very well. 73




Figure 1.a) New artwork for the WWVB Receiver. b) A simple cut-and-jumper fix for the original artwork.