

**Stereo LED Audio Level/VU Meter, June & July 2016:** in the circuit diagram on page 36 of the June 2016 issue and the overlay diagram on page 77 of the July 2016 issue, the  $12k\Omega$  and  $1.5k\Omega$  resistors associated with REG2 are swapped. This error has been carried over onto the PCB silkscreen as well.

Install these resistors in each other's marked positions to get the correct 11V output, otherwise the unit will not power up.

**Touchscreen Appliance Energy Meter, August-October 2016:** in the parts list on page 33 of the August 2016 issue, an incorrect part number was given for the Yunpen YF10T6 mains filter. It should be Jaycar Cat. MS4000.