

**SONY**

# Car Stereo Service Bulletin

Sony Service Company · Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** XR-7150/7180/7200/7280/7400

**No. 175**

**Subject:** Wow Or No Rotation


**Date:** October 15, 1990

**Symptom:**  
(61)

If there is either wow or no rotation due to the falling off of the belt (Ref. No. 212) from the Midway Pulley (Ref. No. 209), perform the following procedure.

**Solution:** If this symptom occurs, please change the Power Arm with an improved one, which includes a pin to avoid the falling off of the belt.

Ref. No.	Description	Part Number	
		Former	New
206	Power Arm Assembly	3-344-107-01	X-3344-139-1



Reference: CS-146

PRINTED IN U.S.A.  
CSA-14990-2

CSA-14  
Radio/Cassette