

# PTV SERVICE CODE - QUICK REFERENCE

A complete list of Service Codes can be found in the PTV & CTV Model-Chassis-Warranty References.

Service Codes are for the use of qualified service technicians only. Damage resulting from the unauthorized use of Service Codes will not be covered under warranty.

***To search for a model, press <Ctrl> + <F>.***

Model	Chassis	Year	Option Menu Code	Circuit Adjust Code	Convergence Adjust Code
WS-48513	V23	2003	0370	0357	0359<4><5><6>
WS-48613	V23	2003	0370	0357	0359<4><5><6>
WS-55513	V23	2003	0370	0357	0359<4><5><6>
WS-55613	V23	2003	0370	0357	0359<4><5><6>
WS-55813	V23	2003	0370	0357	0359<4><5><6>
WS-65513	V23	2003	0370	0357	0359<4><5><6>
WS-65613	V23	2003	0370	0357	0359<4><5><6>
WS-65713	V23	2003	0370	0357	0359<4><5><6>
WS-65813	V23	2003	0370	0357	0359<4><5><6>
WS-73513	V23	2003	0370	0357	0359<4><5><6>
WS-73713	V23	2003	0370	0357	0359<4><5><6>
WL-82913	V23L	2003	0370	0357	N/A
WT-42313	K20	2003	0370	0357	0359<4><5><6>
WT-42413	K20	2003	0370	0357	0359<4><5><6>
WS-48313	V22	2003	0370	0357	0359<4><5><6>
WS-48413	V22	2003	0370	0357	0359<4><5><6>
WS-55313	V22	2003	0370	0357	0359<4><5><6>
WS-55413	V22	2003	0370	0357	0359<4><5><6>
WS-65313	V22	2003	0370	0357	0359<4><5><6>
WS-65413	V22	2003	0370	0357	0359<4><5><6>
WS-48511	V21	2002	2170	2157	2159<4><5><6>
WS-B55	V21	2002	2170	2157	2159<4><5><6>
WS-55511	V21	2002	2170	2157	2159<4><5><6>
WS-55711	V21	2002	2170	2157	2159<4><5><6>
WS-65511	V21	2002	2170	2157	2159<4><5><6>

WS-65611	V21	2002	2170	2157	2159<4><5><6>
WS-65711	V21	2002	2170	2157	2159<4><5><6>
WS-65712	V21	2002	2170	2157	2159<4><5><6>
WS-73711	V21	2002	2170	2157	2159<4><5><6>
WT-A42	VK20	2002	2270	2257	2259<4><5><6>
WT-42311	VK20	2002	2270	2257	2259<4><5><6>
VS-A50	V20	2002	2270	2257	2259<4><5><6>
VS-50111	V20	2002	2270	2257	2259<4><5><6>
VS-60111	V20	2002	2270	2257	2259<4><5><6>
WS-A48	V20	2002	2270	2257	2259<4><5><6>
WS-48311	V20	2002	2270	2257	2259<4><5><6>
WS-A55	V20	2002	2270	2257	2259<4><5><6>
WS-55311	V20	2002	2270	2257	2259<4><5><6>
WS-55411	V20	2002	2270	2257	2259<4><5><6>
WS-A65	V20	2002	2270	2257	2259<4><5><6>
WS-65311	V20	2002	2270	2257	2259<4><5><6>
WS-65411	V20	2002	2270	2257	2259<4><5><6>
WS-73411	V20	2002	2270	2257	2259<4><5><6>
WS-55859	V19	2001	0170	0157	0159<4><5><6>
WS-55909	V19	2001	0170	0157	0159<4><5><6>
WS-65859	V19	2001	0170	0157	0159<4><5><6>
WS-65909	V19	2001	0170	0157	0159<4><5><6>
WS-73909	V19	2001	0170	0157	0159<4><5><6>
WS-55809	V18	2001	0170	0157	0159<4><5><6>
WS-55819	V18	2001	0170	0157	0159<4><5><6>
WS-65809	V18	2001	0170	0157	0159<4><5><6>
WS-65819	V18	2001	0170	0157	0159<4><5><6>
WT-46809	V18	2001	0170	0157	0159<4><5><6>
VS-45609	VZ9	2001	0170	0157	0159<4><5><6>
VS-50609	VZ9	2001	0170	0157	0159<4><5><6>
VS-55609	VZ9	2001	0170	0157	0159<4><5><6>
VS-60609	VZ9	2001	0170	0157	0159<4><5><6>
VS-60719	VZ9	2001	0170	0157	0159<4><5><6>
VS-70709	VZ9	2001	0170	0157	0159<4><5><6>
WS-55908	V17	2001	8270	8257	8259<4><5><6>
WS-65908	V17	2001	8270	8257	8259<4><5><6>
WS-55807	V17	2000	8270	8257	8259<4><5><6>
WS-55857	V17	2000	8270	8257	8259<4><5><6>

WS-55907	V17	2000	8270	8257	8259<4><5><6>
WS-65807	V17	2000	8270	8257	8259<4><5><6>
WS-65857	V17	2000	8270	8257	8259<4><5><6>
WS-65907	V17	2000	8270	8257	8259<4><5><6>
WS-73907	V17	2000	8270	8257	8259<4><5><6>
WT-46807	V17	2000	8270	8257	8259<4><5><6>
VS-45607	VZ8	2000	1270	1257	1259<4><5><6>
VS-50607	VZ8	2000	1270	1257	1259<4><5><6>
VS-50707	VZ8	2000	1270	1257	1259<4><5><6>
VS-55707	VZ8	2000	1270	1257	1259<4><5><6>
VS-60607	VZ8	2000	1270	1257	1259<4><5><6>
VS-60707	VZ8	2000	1270	1257	1259<4><5><6>
VS-70707	VZ8	2000	1270	1257	1259<4><5><6>
VS-45605	VZ7	1999	1270	1257	1259<4><5><6>
VS-50605	VZ7	1999	1270	1257	1259<4><5><6>
VS-50705	VZ7	1999	1270	1257	1259<4><5><6>
VS-55705	VZ7	1999	1270	1257	1259<4><5><6>
VS-60705	VZ7	1999	1270	1257	1259<4><5><6>
VS-70705	VZ7	1999	1270	1257	1259<4><5><6>
VS-50805	V16	1999	1270	1257	1259<4><5><6>
VS-60805	V16	1999	1270	1257	1259<4><5><6>
WS-55805	V16	1999	1270	1257	1259<4><5><6>
WS-55905	V16	1999	1270	1257	1259<4><5><6>
WS-65905	V16	1999	1270	1257	1259<4><5><6>
WS-73905	V16	1999	1270	1257	1259<4><5><6>
WT-46805	V16	1999	1270	1257	1259<4><5><6>
VS-50800	VZ6	1998	1370	2357	2359<4><5><6>
VS-50803	VZ6	1998	1370	2357	2359<4><5><6>
VS-60803	VZ6	1998	1370	2357	2359<4><5><6>
VS-70803	VZ6	1998	1370	2357	2359<4><5><6>
VS-80803	VZ6	1998	1370	2357	2359<4><5><6>
VS-45603	VZ5	1998	1370	2357	2359<4><5><6>
VS-50603	VZ5	1998	1370	2357	2359<4><5><6>
VS-50604	VZ5	1998	1370	2357	2359<4><5><6>
VS-50703	VZ5	1998	1370	2357	2359<4><5><6>
VS-60603	VZ5	1998	1370	2357	2359<4><5><6>
VS-60703	VZ5	1998	1370	2357	2359<4><5><6>
WS-65903	V15	1998	1370	2357	2359<4><5><6>

WS-73903	V15	1998	1370	2357	2359<4><5><6>
TS-50611	VZ4	1997	1370	2357	2359
VS-45501	VZ4	1997	1370	2357	2359
VS-45501A	VZ4	1997	1370	2357	2359
VS-45502	VZ4	1997	1370	2357	2359
VS-50501	VZ4	1997	1370	2357	2359
VS-50501A	VZ4	1997	1370	2357	2359
VS-50502	VZ4	1997	1370	2357	2359
VS-55601	VZ4	1997	1370	2357	2359
VS-60601	VZ4	1997	1370	2357	2359
VS-60621	VZ4	1997	1370	2357	2359
VS-70601	VZ4	1997	1370	2357	2359
TS-50811	V14B	1997	1370	2357	2359
VS-50801	V14B	1997	1370	2357	2359
VS-50802	V14B	1997	1370	2357	2359
VS-60801	V14B	1997	1370	2357	2359
TS-4545	VZ3	1996	1370	2357	2359
TS-5045	VZ3	1996	1370	2357	2359
TS-5545	VZ3	1996	1370	2357	2359
VS-4543	VZ3	1996	1370	2357	2359
VS-4544	VZ3	1996	1370	2357	2359
VS-5043	VZ3	1996	1370	2357	2359
VS-5044	VZ3	1996	1370	2357	2359
VS-5047	VZ3	1996	1370	2357	2359
VS-6043	VZ3	1996	1370	2357	2359
VS-6047	VZ3	1996	1370	2357	2359
TS-5089	V14	1996	1370	2357	2359
VS-5077	V14	1996	1370	2357	2359
VS-5078	V14	1996	1370	2357	2359
VS-6087	V14	1996	1370	2357	2359
VS-7087	V14	1996	1370	2357	2359
VS-8087	V14	1996	1370	2357	2359
TS-4557	VZ2B	1995	1370	2357	23595
TS-5057	VZ2B	1995	1370	2357	23595
VS-5059	VZ2B	1995	1370	2357	23595
VS-6055	VZ2B	1995	1370	2357	23595
VS-4541	VZ2	1995	2358	2357	23595
VS-4542	VZ2	1995	2358	2357	23595

VS-5041	VZ2	1995	2358	2357	23595
VS-5042	VZ2	1995	2358	2357	23595
VS-6041	VZ2	1995	2358	2357	23595
TS-5087	V14	1995	1370	2357	23595
VS-5075	V14	1995	1370	2357	23595
VS-5076	V14	1995	1370	2357	23595
VS-6085	V14	1995	1370	2357	23595
VS-7085	V14	1995	1370	2357	23595
TS-4553	VZ2	1994	2358	2357	23595
TS-5053	VZ2	1994	2358	2357	23595
VS-4551	VZ2	1994	2358	2357	23595
VS-4551A	VZ2	1994	2358	2357	23595
VS-4552	VZ2	1994	2358	2357	23595
VS-4552A	VZ2	1994	2358	2357	23595
VS-5051	VZ2	1994	2358	2357	23595
VS-5052	VZ2	1994	2358	2357	23595
VS-5055	VZ2	1994	2358	2357	23595
VS-5055C	VZ2	1994	2358	2357	23595
VS-6051	VZ2	1994	2358	2357	23595
VS-6051C	VZ2	1994	2358	2357	23595
VS-5073	V13B	1994	2358	2357	23595
VS-5074	V13B	1994	2358	2357	23595
VS-6083	V13B	1994	2358	2357	23595
VS-7083	V13B	1994	2358	2357	23595
TS-4573	V13	1994	2358	2357	23595
VS-5072	V13	1994	2358	2357	23595
VS-4571	V13	1993	2358	2357	23595
VS-4571C	V13	1993	2358	2357	23595
VS-5071	V13	1993	2358	2357	23595
VS-5081	V13	1993	2358	2357	23595
VS-6071	V13	1993	2358	2357	23595
VS-6081	V13	1993	2358	2357	23595
VS-7071	V13	1993	2358	2357	23595