100-WATT INVERTER

transistors T4-T7 to the centre-tap of inverter transformer (X2) was found missing in the circuit forming a part of my article in Jan. '83 issue. Readers are requested to make a note of this correction. Sorry for

A line interconnecting the collectors of

make a note of this correction. Sorry for the inconvenience! PRADEEP SHARMA New Delhi