

Digital Trigger Adapter for Scopes
(April 1995): The PCB overlay diagrams on page 85 were printed incorrectly, with the component outline information not reproduced at all. The diagrams on the right show (hopefully!) the overlays as they should have been printed. Our apologies for this problem, even though not of our making.

