

- There is an error in my “Emergency Electronic Ignition” article (October 1988). The value of R3 is 1,000 ohms—not the 100 ohms shown. Readers should

*(continued on page 70)*