In "The Morse-A-Word, Part One: Theory and System Operation" (March 1979), in Fig. 2, there should be a pin 9 on IC5 connected to pin 6 of IC11. The foil pattern for the pc board, shown as Fig. 6 in Part Two of the arti-

microvoits.

cle in the April issue, supplies the necessary connection. **POPULAR ELECTRONICS**