

Corrections & Updates

FPGA Prototyping Board

March 2006, ref. 050370-1

A small number of FPGA Prototyping Boards from the first production batch have six SMD electrolytic capacitors fitted the wrong way around: C5, C6, C7, C13, C14 and C15.

The dash on these capacitors has to be at the side of the connectors. If they are at the side of the LCD, there are two options:

1. you remove the capacitors and refit them with the correct orientation;
2. you return the FPGA board to us and we will do the above free of charge.

In any case, do not apply the supply voltage before it has been ascertained that the six electrolytics are fitted the right way around.