

Playmaster 300W subwoofer amp
(April 1995): The amp module's schematic on page 61 shows D4 connected the wrong way around — it's anode should face C16. The PCB overlay in the May issue is correct.