Roulette Wheel (April 1995): The PCB overlay diagram on page 50 was again printed incorrectly, with the component outline information missing. As before, the diagram is hopefully reproduced correctly on the facing page.







