

In "Single-Tone Paging for Wilson HTs," December, 1980, pp. 112-114, several errors managed to creep in, not the least of which was the author's old callsign. Fred's call is W4CK.

On page 112, zener D2 in Fig. 1 should be a 1N751A. This change should be reflected in the parts list on page 114, too. Also, on page 113, column 1, at the beginning of the bottom paragraph, the opening line should read "There is no *disad-*

vantage in. . ."

An improvement over the insulation technique described on page 114, column 2, lines 19 through 25, would be to use non-conducting styrofoam cut to the shape of the PCB.

Finally, at the bottom of the parts list, time and inflation have had their effect. Microsizer Co. (at the same address) now offers the kit for \$17.95 and the PCB alone for \$4.50.

Gene Smarte WB6TOV
News Editor