

# Corrections & Updates

## USB Data Acquisition Card

November 2007, p. 16-20, ref. 070148-1

In the circuit diagram, the USB+ and USB- pins on K2 should be swapped. The PCB track layout shown in the article should also be corrected. PCBs supplied through the Elektor Shop have the correct USB signal routing and are **not** affected.

Although different values are indicated in the circuit diagram and the parts list, both 27  $\Omega$  and 33  $\Omega$  resistors may be used in positions R3 and R4.

