

FLUORESCENT LIGHT STARTER (October 1982, File No. 2/PC/33): Some have been sold with a $0.1\mu\text{F}/400\text{VW}$ capacitor. This must be a 250VAC unit as originally specified otherwise there is a fire risk. Also, if some tubes prove difficult to start, the $.015\mu\text{F}$ capacitor may be altered to $0.1\mu\text{F}$. Finally, the rating for the 56Ω resistor should be $\frac{1}{2}\text{W}$.