CORRECTIONS

A sharp reader pointed out to me that there were errors in the formulas in my article, "Build an Autoranging Capacitance Meter" (Popular Electronics, January 1996). Here are the corrected formulas:

$$C = 1.44/(R1 + 2R2)f$$

 $R11 = ((3,000,000 - R9)/2) - R10$
 $R8 = ((30,000 - R6)/2) - R7$
 $R5 = ((300 - R3)/2) - R4$

The formulas were correct in my original article but were typeset improperly. The Gernsback BBS phone number was also printed incorrectly; the correct number is 516-293-2283.

-Robert Gotchall