



In our October issue, Figure 19 on page 93, in the story "Unicorn Robot," is shown without dimensions. Here is the correct Fig. 19.

burning, not because of an overheating problem. The method is both safe and convenient.

L. SCOTT HOFER  
Federal Way, WA

R-E



ALL DIMENSIONS  
IN INCHES